

## **Service Bulletin**

File in Section:

Bulletin No.: 17-NA-294

Date: September, 2017

## **TECHNICAL**

Subject: Radio Control Display is Scrambled, Split, Pixilated, or Displays Vertical Lines

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
Біапи.	wiodei.	from	to	from	to		
Chevrolet	Traverse	2018	2018			All	All




Copyright 2017 General Motors LLC. All Rights Reserved.


Page 2 September, 2017 Bulletin No.: 17-NA-294







4860732



4860735

Upon inspection, the technician will not find any related codes stored and normal audio from the speakers will be experienced as well.

	Cause	This may be the result of the internal memory being overwritten during certain module communication sequences.		
Γ	Correction	If this concern is encountered, replace the radio control (ICS) assembly.		

## **Service Procedure**

If you encounter a vehicle with the above concern, replace the radio control (ICS) assembly. Refer to Radio Control Assembly Replacement with IO5, IO6 in Service Information for detailed instructions.

## **Warranty Information**

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
3420700	Radio Control Assembly Replacement	Use Published Labor Operation Time

Version	1
Modified	