



Service Bulletin

File in Section: -


Bulletin No.: 17-NA-295

Date: September, 2017

TECHNICAL

Subject: Rattle Type Noise Heard in Cargo Area and/or Missing Tire Inflator Spacer in the Inflator Kit

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Volt	2017	2018				

Involved Region or Country	North America Only
Condition	Some customers may comment on a rattle type noise heard in cargo area and/or missing tire inflator spacer in the inflator kit.
Cause	

4481731



4481718

This condition may be caused by a missing cardboard spacer for the tire inflator bag that was not installed at the assembly plant.

Correction

Install new cardboard spacer for the tire inflator bag

Parts Information

Causal Part	Description	Part Number	Qty
X	SPACER-TOOL STOW COMPT	23276300	1

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
8080348*	Installing Tire Inflator Bag Cardboard Spacer	0.2 hr
*This is a unique Labor Operation for Bulletin use only.		

Version	1
Modified	Released September 18, 2017

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION