




# Service Bulletin

File in Section: -  
 Bulletin No.: 17-NA-296  
 Date: September, 2017

## TECHNICAL

**Subject:** Noise Originating from Front Suspension When Traveling Over Bumps

| Brand:    | Model: | Model Year: |      | VIN: |    | Engine: | Transmission: |
|-----------|--------|-------------|------|------|----|---------|---------------|
|           |        | from        | to   | from | to |         |               |
| Chevrolet | Spark  | 2016        | 2017 |      |    | All     | All           |

|                                   |   |
|-----------------------------------|---|
| <b>Involved Region or Country</b> | North America and Export Regions  |
| <b>Condition</b>                  | Some customers may comment on a noise originating from the front of the vehicle when traveling over bumps.                                      |
| <b>Cause</b>                      |  <p style="text-align: right; font-size: small;">4867096</p> |
| <b>Correction</b>                 | If wear marks are observed like shown above, replace the coil spring with new part.   |

### Service Procedure

If you encounter a vehicle with the above concern and witness marks are observed, replace the affected spring. Refer to *Strut, Strut Component, or Spring Replacement* in SI.

### Parts Information

| Causal Part | Description                              | Part Number |
|-------------|--|-------------|
| X           | SPRING-FRT COIL (Manual Transmission)    | 42593054    |
| X           | SPRING-FRT COIL (Automatic Transmission) | 42593055    |

## Warranty Information

For vehicles repaired under warranty, use:

| Labor Operation | Description                                   | Labor Time                         |
|-----------------|---|------------------------------------|
| 8033790         | Strut, Strut Component, or Spring Replacement | Use Published Labor Operation Time |

|          |   |
|----------|---|
| Version  | 1 |
| Modified |   |

