



Technical Journal

TITLE:

Improved low fuel indication

REF NO: TJ 32209.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2016-12-20	STATUS DATE: 2016-12-29
FUNC GROUP: 3811	FUNC DESC: Combined instrument, complete	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234							2017-2017		-	201617-201651
256							2016-2017		-	201505-201651

CSC Customer Symptom Codes

Code	Description
GK	Trip computer/Current fuel consumption faulty presentation
HJ	Warning lights and chimes/Fuel level indication/no indication

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

DTC Diagnostic Trouble Codes

Text

**DESCRIPTION:**

A more detailed low fuel indication can be added in the DIM (Driver Information Module).
A text message which the driver has to actively acknowledge in order to remove it will be displayed when the fuel level is low.

SERVICE:

Perform a Total Upgrade according to TJ 31543.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 3811.