



Technical Journal

TITLE:
Climate system, high fan speed noise

REF NO: TJ 32139.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2017-01-03	STATUS DATE: 2017-01-06
FUNC GROUP: 8730	FUNC DESC: Climate unit	Page 1 of 2	

“Right first time in Time”

Attachment

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
234							2017-2017		0000350-0011795	201617-201646
256							2016-2017		0000561-0151793	201505-201646

CSC Customer Symptom Codes

Code	Description
8F	Blower fan/Unusual noise

VST Operation Number

VST Operation Number	Description
36004-2	Software control module downloading

DTC Diagnostic Trouble Codes

Text

**DESCRIPTION:**

*CCM: Climate Control Module

*TJ: Technical Journal

Customer may experience a high fan speed noise regardless of the fan speed selection. This may be due to accidentally touching the 2nd row display. A new logic in the CCM software was implemented 2016w46, that allows rear climate display to start in default mode 72/72 Auto with fan level 2. This will take place after every restart of engine.

SERVICE:

Perform Total Upgrade according to TJ-31543.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8730.