



Technical Journal

TITLE:
Creaking noise from Steering Wheel Module

REF NO: TJ 32198.3.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2017-01-13	STATUS DATE: 2017-01-18
FUNC GROUP: 6415	FUNC DESC: STEER WHEEL, COLUMN, COLUMN LOCK, SHAFT	Page 1 of 3	

“Right first time in Time”

Attachment

File Name	File Size
TJ 32198.PNG	2.4698 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256							2016	21	0000001-0079554	201505-201610

CSC Customer Symptom Codes

Code	Description
H4	Steering/Unusual noise/Unsure when/at all times
X8	Steering/Unusual noise/At full turn

VST Operation Number

VST Operation Number	Description
98654-2	Steering Wheel adjust acc. to TJ32198

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

**DESCRIPTION:**

If creaking/ticking noise from release pin on SWM when turning the Steering wheel follow advice under Service.

SERVICE:

* Mount Velour tape (cut off a piece 10x15mm from Part nr.1161842) on the steering wheel, according to the attachment TJ 32198.PNG

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 6415. Also attach a sound file in to the report.

To view TJ attachment continue to next page. This TJ has one attachment.

