



Parts Bulletin

TITLE:

**S89809:Trim Molding Side Doors
Model Year 2017 S90**

GROUP:
84

CAT/NO:
S89809

REFERENCE BULLETINS:
TJ 32228, QB S89809

CAR MARKET:
United States and Canada

COPY TO / CIRCULATIONS (PLEASE INITIAL):

ISSUE DATE:
2017-02-03

STATUS DATE:
2017-02-03

**GENERAL
MANAGER**

**PARTS
MANAGER**

**SERVICE
MANAGER**

**SALES
MANAGER**

Page 1 of 1

“Right first time in Time”

Reference Bulletins: TJ 32228, QB S89809

Volvo Car USA LLC and Volvo Car of Canada Ltd (Volvo) on behalf of Volvo Car Corporation, has decided to launch Service Campaign S89809 on certain model year 2017 S90 vehicles.

Volvo has identified that the exterior door trim moldings may crack.

The corrective action is to replace all four (4) exterior trim moldings on eligible vehicles.

Service Action S89809 affects 909 vehicles in the U.S. and 82 in Canada.

RETAILER MUST CONFIRM VEHICLE ELIGIBILITY PRIOR TO BEGINNING THE REPAIR FOR THIS ACTION.

Vehicles in retailer inventory must be upgraded prior to sale.

PLEASE NOTE: Service Action S89809 will be in effect until **December 31, 2018** regardless of mileage.

The following part numbers apply:

Part Number	Description	Qty
31672262	Trim Molding	1
31672263	Trim Molding	1
31672264	Trim Molding	1
31672265	Trim Molding	1
31480527	Primer (US)	0.2
31480528	Primer (CA)	0.2