



Technical Journal

TITLE:

P5-XC90 Front license plate screws

REF NO: TJ 31218.1.3	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2017-02-08	STATUS DATE: 2017-02-13
FUNC GROUP: 8611	FUNC DESC: Bumper, front	Page 1 of 3	

“Right first time in Time”

Attachment

File Name	File Size
Wurth 02151012.jpg	2.4353 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
256							2016-2017		-	201545-999952

CSC Customer Symptom Codes

Code	Description
ZW	Exterior/Component exterior wrong installation/missing

VST Operation Number

DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

**DESCRIPTION:**

*Update screw part number

A new front license plate frame was introduced on MY16 XC90 2015w45. The H frame P/N (part number) 31391625 is no longer needed.

SERVICE:

Install front license plate using four (4) Wurth screws P/N 02151012. (For claiming use P/N 2151012)

*Canadian market use Wurth screw P/N 140.70604 (For claiming use P/N 2151012)

VEHICLE REPORT:

When submitting a Vehicle Report for a condition described in this TJ, use concern area "Vehicle Report and sub concern area "Support Not Needed" with function group 8611.

To view the TJ attachment continue to next page. This TJ has one attachment.

