



Parts Bulletin

TITLE:
S89833 Replace Headliner Clip

GROUP: 85	CAT/NO: S89833	REFERENCE BULLETINS: QB S89833, TJ 32612	CAR MARKET: United States and Canada	
COPY TO / CIRCULATIONS (PLEASE INITIAL):			ISSUE DATE: 2017-04-11	STATUS DATE: 2017-04-11
GENERAL MANAGER	PARTS MANAGER	SERVICE MANAGER	SALES MANAGER	
				Page 1 of 1

“Right first time in Time”

Reference Bulletins: QB S89833, TJ 32612

Volvo Car USA LLC and Volvo Car of Canada Ltd (Volvo) on behalf of Volvo Car Corporation, has decided to launch Service Action S89833 on certain model year 2017 S90 vehicles.

Volvo has identified that the headliner may become loose at the rear window.

The corrective action is to replace the rear headliner clip.

Service Action S89833 affects 5,002 vehicles in the U.S. and 230 in Canada.

The following part numbers apply:

Part Number	Description	Qty
31672606	Headliner Clip (Charcoal)	1
31672607	Headliner Clip (Blond)	1