



# Parts Bulletin

TITLE:

**Service Action S39816: VDDM PBL Upgrade  
Model Year 2016-2017 XC90, & 2017 S90, V90CC, V90**

<b>GROUP:</b> 36	<b>CAT/NO:</b> S39816	<b>REFERENCE BULLETINS:</b> TJ 32591, QB S39816	<b>CAR MARKET:</b> United States and Canada	
<b>COPY TO / CIRCULATIONS (PLEASE INITIAL):</b>			<b>ISSUE DATE:</b> 2017-04-26	<b>STATUS DATE:</b> 2017-04-26
<b>GENERAL MANAGER</b>	<b>PARTS MANAGER</b>	<b>SERVICE MANAGER</b>	<b>SALES MANAGER</b>	
				<b>Page 1 of 1</b>

**“Right first time in Time”**

**Reference Bulletins: TJ 32591, QB S39816**

Volvo Car USA LLC and Volvo Car of Canada Ltd (Volvo) on behalf of Volvo Car Corporation, has decided to launch Service Campaign S39816 on certain model year 2016 - 2017 XC90 and 2017 S90, V90CC and V90 vehicles.

Volvo has identified that due to a software deviation in the Vehicle Dynamics Domain Master (VDDM) Primary Boot Loader (PBL), the vehicle may not start after it has been parked and the parking brake lamp will be lit in the instrument panel.

The corrective action is to perform a VDDM PBL software upgrade.

Service Action S39816 affects 54,316 vehicles in the U.S. and 4,479 in Canada.

The following part numbers apply:

<b>Part Number</b>	<b>Description</b>	<b>Qty</b>
31483300	VDDM PBL Software Upgrade (XC90)	1
31682450	VDDM PBL Software Upgrade (S90, V90, V90CC)	1