



ARTICLE: L-17-10-02

DATE: 10/11/2017

Team Tips



Published for GEM Dealerships, Distributors, and Service Technicians

SUBJECT: MY16-18 GEM Steering Wheel Alignment

MODELS: 2016-2018 GEM e2, e4, e6, eL XD

Polaris has identified that some GEM vehicles were manufactured with improper steering wheel alignment. This team tip is to inform dealers of an updated procedure in the service manual to show an easier and alternative method to remove and align the steering wheel.

If you encounter a 2016-2018 GEM e2, e4, e6, eL, or XD model that requires the steering wheel to be removed or aligned, reference the following procedure in the service manual.

Steering Wheel Removal / Installation (EPS)

Steering Wheel Removal / Installation (non-EPS):

ADDITIONAL REFERENCE MATERIALS

2016-2018 GEM e2 / e4 / e6 / eL XD Service Manual: PN 9928618 R02