

SERVICE ALERT

[Print](#)

Date: 2017-01-13

[Close](#)

Service Alert
No: SA-001347

Subject: 2013-2015 CX-5 - MIL LIGHT AFTER PCM REPROGRAMMING

2013-2015 CX-5 Check Engine light (with DTCs P0101, P061B, P2122, P2138) may illuminate after PCM reprogramming due to a mislogic detection in the PCM calibration, available in the current IDS version 103.03. Please uninstall IDS and install version 103.00 to prevent this situation and **"Do Not Update IDS Until Further Notice"**.

Please use the procedure to reflash the PCM back to the previous level. [CLICK HERE for instructions](#)