



<b>Subject:</b>  2017-2018 CX-5, 2018 MX-5, 2018 CX-9 - DIRECT TYPE TIRE PRESSURE MONITORING SYSTEM (TPMS)	<b>Service Alert No.:</b> SA-073/17
	<b>Last Issued:</b> 11/29/2017

## DESCRIPTION

Mazda is incorporating a "Direct" type TPMS, which is unlike the previous "Indirect" type system.

With the "Direct" type TPMS.....

- **there is no TPMS switch on the dashboard.** It is no longer needed.
- the wheel sensors activate **after** detecting tire rotation.
- the wheel sensors transmit data to the vehicle at a rate of **once per minute.**
- the vehicle must be driven at **16 mph or more for two (2) minutes or more** to obtain IDS readings.
- it is necessary to complete the diagnosis **before** turning the ignition OFF, otherwise, the data will be deleted.

**CONSUMER NOTICE:** The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.