

Reference	SSM73641
Models	Discovery / L462 Discovery Sport / L550 Range Rover / L405 Range Rover Evoque / L538 Range Rover Sport / L494
Title	Service Actions N025/ N118/ N120 L462 Excluded
Category	Electrical
Last modified	21-Nov-2017 00:00:00
Symptom	204000 Instrumentation

Content

Issue: Following launch of Service Action N025/ N118/ N120 it is evident that L462 Discovery has been excluded. This is only a temporary position and will be included in a future update to the publications on TOPIx.

Cause: New software for L462 only, currently under development.

Action: Please carry out the above Service Actions to all applicable vehicles with reference to Direct Dealer Warranty. It is anticipated L462 Discovery will be included and publications updated during January 2018.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.