

DTNA Solutions > Service Solutions > Freightliner
> SS 1033208TBB TM21 Dual AC alignment and not seate...

SS 1033208TBB TM21 Dual AC alignment and not seated properly on the pulley

This Service Solution does not imply any special warranty coverage. Standard warranty guidelines and coverage apply. This Service Solution is provided to assist Dealers/Customers in resolving the issue of Dual AC alignment and not seated properly on the pulley.

Applicable Vehicles

HDX/ ISB

Symptoms

Belt roll off

Solution

Crank pulley as been design to have it replaced with TBB 210263 (DTNA#01-33776-000) and new Belt TBB 210264 (DTNA #01-32766-408)

Note# Cummins Adapter 3957841 is needed and (6) 3968075 Fastener. Refer to Cummins installation for torque values

Labels :

EngineTransmission Cooling | and HVAC

Powertrain & Driveline

TBB

ac belt

Add tags

Attachments



