

DTNA Solutions > Service Solutions > Freightliner
> SS 1033180 BHM Fault Code SPN 524251 FMI 7 - Extr...

SS 1033180 BHM Fault Code SPN 524251 FMI 7 - Extra Smart Switch

BHM Fault Code SPN 524251 FMI 7

Applicable Vehicles

M2, 108SD, and 114SD

Issue

BMH fault code 524251/7 is not defined.

Solution

BHM fault code 524251/7 indicates an extra smart switch is installed - same as fault code 6920/7.

Labels :

108SD114SD

Business Class M2

Electronics | Controls | Configuration | Communication | and Diagnostics

Freightliner

bhm

Add tags



4 Kudos

Powered by
Khoros 