

# SS 3704 Cascadia Fault codes 6.0

## APPLICABILITY:

This solution applies to Cascadia Vehicles with Software version 6.0. Service Bulletin 54-239 can be reference for ECU compatibility to reference the software versions to ECUs. Version 6.0 software was installed on new vehicles built after August 1, 2010.

## SOLUTION:


Attached is a copy of the 6.0 Can codes.

Solution ID: 3704

Add tags

## Attachments



 13 Kudos

## Comments



William\_Loehr

01-12-2015 03:05 PM

FYI, MSF code 523544/31 can also be caused by a faulty stalk switch. I also had to disconnect all power to truck, plug in new stalk switch then power back up to get the code to go inactive.



Rob\_\_Chojnowski

06-03-2015 09:39 AM

CAN NOT FIND CODE 639/2 OR 524286/5. 639 CODE FOR HVAC-P3-F- HVAC CASCADIA, AND 524286 CODE FOR COMMUNICATIONS UNIT, CELLULAR



Curt\_Granade

07-14-2017 08:27 AM

I entered fault code 522116/2 it goes to another type of fault

Powered by  
**Khoros** 