



NUMBER: 02-008-17

GROUP: 02 - Front Suspension

DATE: November 1, 2017

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

SUBJECT:

Servicing Lower Control Arm Inner Pivot Bushings

OVERVIEW:

This bulletin discusses replacement of the lower control arm inner pivot bushings.

MODELS:

2015 - 2018	(LA)	Dodge Challenger
2011 - 2014	(LC)	Dodge Challenger
2011 - 2018	(LD)	Dodge Charger
2011 - 2018	(LX)	Chrysler 300

NOTE: This bulletin applies to vehicles within the following markets/countries: EMEA.

DISCUSSION:

This information only Service Bulletin is being released to inform technicians that the lower control arm pivot bushings are now serviceable. Complete replacement of the lower control arm for inner pivot bushing failure is no longer required.

For pivot bushing replacement, refer to the detailed service procedures available in DealerCONNECT> TechCONNECT under: Service Info>02 - Front Suspension/Front/Bushing(s), Lower Control Arm/Removal/Installation.

PARTS REQUIRED:

Qty.	Part No.	Description
1 (AR)	68399084AA	Inner Pivot Bushing Kit (Sales Codes SDG, SDC or SDX)
1 (AR)	68399085AA	Inner Pivot Bushing Kit (Sales Codes SDD, SDB, SDE or SDF)
1 (AR)	68399086AA	Inner Pivot Bushing Kit (LX vehicles with Sales Codes SDG, SDC or SDX)

POLICY:

Information Only