GPOP - Issue Review System

Part Number: 05074256A\$, 68269772A\$, 68269773A\$, 05074257A\$, 55113660A\$, 55113661A\$

Part Description: Door Hinge Assembly

Issue Side door hinge noisy. Only replace the door hinge with the integral check device.

Description: Do not replace the simple hinge if it is not damaged it is not the source of the noise.

Replacing it unnecessary and is an over-repair.

Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.