



NUMBER: 23-012-17

GROUP: Body

DATE: March 03, 2017

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 17-021. ALL APPLICABLE UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE UN-SOLD VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. FOR VEHICLES NOT INCLUDED IN THE RRT VIN LIST, APPLICATION OF THIS SERVICE BULLETIN TO SOLD UNITS IS BASED UPON THE CUSTOMER EXPERIENCING THE SYMPTOM/CONDITIONS. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Wheel Liner Push Pin Fastener Replacement

OVERVIEW:

This bulletin involves replacing both wheel liner push pin fasteners at the front fenders.

MODELS:

2017 (LD) Dodge Charger

NOTE: This bulletin applies to vehicles within the following markets/countries: EMEA, NAFTA, LATAM and APAC.

NOTE: This bulletin applies to vehicles built on or before February 02, 2017 (MDH 0202XX).

SYMPTOM/CONDITION:

The customer may describe a rattle from the left, right or both, front wheel openings while driving. This condition is caused from one or both plastic front wheel liner fasteners loosening from their locations.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

PARTS REQUIRED:

Qty.	Part No.	Description
2	06506007AA	Rivet

REPAIR PROCEDURE:

1. Turn the steering wheel to full stop one direction at a time and remove both the left and right push fasteners from each wheel liner (Fig. 1). Discard fasteners.



Fig. 1 Old Fastener

2. Using a hand plastic rivet tool, install two new rivets on the left and right wheel liners.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-02-09-94	Wheel Liner Fastener - Replace (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------