



NUMBER: 23-033-17

GROUP: 23 - Body

DATE: July 27, 2017

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

THIS SERVICE BULLETIN IS ALSO BEING RELEASED AS RAPID RESPONSE TRANSMITTAL (RRT) 17-069. ALL APPLICABLE SOLD AND UN-SOLD RRT VIN's HAVE BEEN LOADED. TO VERIFY THAT THIS RRT SERVICE ACTION IS APPLICABLE TO THE VEHICLE, USE VIP OR PERFORM A VIN SEARCH IN TECHCONNECT. ALL REPAIRS ARE REIMBURSABLE WITHIN THE PROVISIONS OF WARRANTY.

SUBJECT:

Paint Delamination On Front Door Panel Pull Cups (Door Pulls)

MODELS:

2016 (B1) Jeep Renegade

NOTE: This bulletin applies to vehicles within the following markets/countries: LATAM.

NOTE: This bulletin applies to vehicles built on or after March 01, 2016 (MDH 0301XX) and on or before July 06, 2016 (MDH 0706XX).

SYMPTOM/CONDITION:

The customer may describe paint peeling on the left, right, or both front door panel pull cups.

DIAGNOSIS:

If a customer's VIN is listed in VIP or your RRT VIN list, perform the repair.

PARTS REQUIRED:

Qty.	Part No.	Description
1	735603977	Pull-Cup Left Side
1	735603945	Pull-Cup Right Side

REPAIR PROCEDURE:**NOTE: Procedure is the same for both front doors on the vehicle.**

1. Open the door.
2. Remove the pull cup rubber mat (Fig. 1) from the pull cup.
3. Remove the screw holding the pull cup to the door panel (Fig. 1) .




Fig. 1
Rubber Mat and Pull Cup

- 1 - Rubber Mat
2 - Screw
-

4. Remove and discard the pull cup from the door panel.
5. Install the new pull cup on the door panel.
6. Install the screw on the pull cup. Tighten screw securely.
7. Install the pull cup rubber mat on the pull cup.
8. Close the door.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
23-20-23-96	Cup Pull, Replace Both Sides (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------