

## GPOP - Issue Review System

**Part Number:** 68326162A\$, 68326163A\$, 68326164A\$

**Part Description:** Powertrain Control Module

**Issue Description:** Customer may experience a MIL-on condition with a P0607 - ECU INTERNAL PERFORMANCE fault in the Powertrain Control Module (PCM). This fault may occur due to a software anomaly and a combination of actions taken by the driver.  
DO NOT REPLACE THE PCM AT THIS TIME.  
Please erase the fault and return the vehicle to the customer. A resolution for this condition is under development.

Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related only to this GPOP TechTip. Please include the Part Number(s) and TechTip Part Description of the TechTip you are referencing for our tracking system.

---