

9003790

10/04/2017

MY15 - 17

All Makes

All bodies

GPOP - Issue Review System

Part Number: 05184595A\$, 05184596A\$, 05184068A\$, 05184069A\$

Part Description: Valve Cover and Gasket, Left and Right

Issue Description: Pertains to vehicles equipped with a 3.6L V6 V.V.T. Engine only: Oil leaking from the valve cover onto the O2 sensor causing faults codes P0140, P2096, P0137, P0157. Need to verify the leak source and cause (gasket pinched, out of position, rolled, or cut). Please call one of the individuals below before proceeding with the repair. Also, if possible take a picture and send it to the emails listed below.

First: Scott Knaggs - Cell (313) 363-6937 scott.knaggs@facgroup.com

Second: Joe Lovell - Cell (734) 309-6467 joe.lovell@fcagroup.com

If no response in 15 minutes, proceed with repair.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system
