

9003807

10/18/2017

MY14

KL

## **GPOP - Issue Review System**

**Part Number:** 05150843A\$, 05150790A\$, 1UV93DX9A\$, 1VH37DX9A\$, 1ZX43DX9A\$,  
1ZX44DX9A\$, 1ZX45DX9A\$, 68103284A\$, 68103285A\$, 68223058A\$,  
68223051A\$

**Part Description:** HVAC Control, Actuator, Powertrain Control Module (PCM)

**Issue** MIL light for B104E Blend door circuit High (stored).

**Description:** The HVAC temperature door feedback voltage is monitored by the PCM. If the PCM detects a loss of voltage from the HVAC Temperature door it may set a B104E in the PCM. If B104E is set in the PCM please refer to the service manual for Fault Code: B104E. Please call George Sakr at cell (248) 613-7319. If no response in 15 minutes, proceed with repair.

There are no Powertrain components that need to be changed for this condition.

~\_\_\_\_\_  
Contact us at [CAGRIS@Chrysler.com](mailto:CAGRIS@Chrysler.com) for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.