GPOP - Issue Review System

Part Number: 05011432A\$, 05011431A\$

10/25/2017

Part Description: Rocker Arm

Issue If normal diagnosis has led to a broken rocker arm, please replace all 12 rockers. Description: Contact Stephen Alvarado at the STAR Center at (866) 799-1695 ext. (4720271) to

arrange a fast track return for the parts. Cummins engineering is currently investigating the root cause to this condition and would like to get these parts back

for analysis.

Contact Us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. DO NOT email regarding repair procedures unrelated to this Tech Tip or part order inquires. Please include the Part Number (s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.