

SSM  
46336

Some 2016-2017 F-650/750 vehicles requiring a BCM replacement have resulted in an Integrated Diagnostic System (IDS) message stating the BCM part number is not recognized during the programmable module installation (PMI) procedure. When replacing a BCM, use IDS release 103.05 or higher.