

SSM  
46346

Some 2015-2016 F-150 SuperCrew vehicles equipped with the vista roof opening panel may exhibit a water leak from the roof opening panel area. Refer to Workshop Manual (WSM) Section 501-17 for water leak diagnosis. If test results lead to replacement of roof opening panel glass install part number FL3Z-16500A18-E which has a revised seal. Use casual part 16500A18 and applicable labor operations in section 12 of the service labor time standards (SLTS) manual.