

SSM
46367

Some 2016 Edge, F150, Explorer, and Mustang vehicles equipped with a MyFord display 4 inch screen may exhibit a blank screen and no audio. Reprogram the front control display interface module (FCDIM) to the latest calibration using Integrated Diagnostic System (IDS) release 104.01 or higher. Make sure you are connected to the internet when entering module programming to obtain the latest updates. Calibration files may also be obtained at www.motorcraftservice.com. Use causal part number 10D885 and applicable labor operations in section 10 of the Service Labor Time Standards (SLTS) manual.