

SSM  
46372

Some 2017 F-150 Raptor vehicles may exhibit the bumper tow hook trim piece not properly positioned in the front bumper. Front bumper removal is not necessary to properly reposition the trim piece.