

SSM  
46416

Some 2017 F-Super Duty and 2016-2017 F-650/F-750 vehicles equipped with a 6.7L engine may exhibit a DTC P0000. This DTC is due to a processing error in the powertrain control module (PCM) as a result of on demand self testing with an Integrated Diagnostic System (IDS). P0000 is an invalid DTC that will not illuminate the MIL and should be disregarded.