

TOL NOTICE (US&CAN) – February 9, 2017

**Update to Technical News Item 171.1:
*Thruxton 1200R Front Brake Calipers***

IMPORTANT NOTE: It has come to our attention that a step has been omitted from the Wheel Spacer Fitment procedure set out in Technical News 171 (section 171.1). After the new 24.6mm grooved spacers have been installed (step 3), the air gap between the wheel speed sensor and the pulser ring must also be measured and adjusted if required as described in the service manual.

Please mark your copy of Technical News 171 with this information. The procedure will be updated and included in Technical News 174.

If you have any questions, contact your Regional Manager or call Triumph 24/7 Customer Support at (888) 284-6288.

TRIUMPH MOTORCYCLES AMERICA