

SSM  
46422

Some 2017 Super Duty vehicles built on or before 05-Dec-2016 may exhibit inoperative interior lamps, moonroof and/or sunshade with no diagnostic trouble code (DTC) being present in the body control module (BCM). This may be caused by a pinched wire at the right and/or left side sun visor mount of the interior lamp feed body harness. Before attempting diagnosis or repairs, inspect the sun visor mount area for pinched wiring.