

SSM
46426

Some 2017 Continental vehicles may exhibit a front right side and/or front left side power seat switches which are inoperative. The memory preset buttons may also be inoperative. Reprogram the drivers seat module (DSM) using IDS software 104.03 or higher. Make sure you are connected to the internet when entering module programming to obtain the latest updates. Calibration files may also be obtained at www.motorcraftservice.com. For claiming, use causal part 14C708 and applicable labor operations in section 10 of the service labor time standards (SLTS) manual.