

Reference	SSM73160
Models	Range Rover / L405 Range Rover Sport / L494
Title	AEB Intiialising or AEB Not available Displayed On Message Centre
Category	Electrical
Last modified	16-Mar-2017 00:00:00
Symptom	206000 Warning Indicators

Content **Issue:**
A customer may report an intermittent concern on Range Rover/ Range Rover Sport 17MY only, that the message 'AEB Initialisation' or 'AEB not available' is displayed on the Instrument Cluster Message Centre.

Cause:
A software conflict producing various Diagnostic Trouble Codes including U3000-96 to be stored in the Image Processing Module A (IPMA).

Action:
Please do not continue with any further diagnosis or component replacement. Landrover will release a solution and communication planned for Pathfinder release 59 on 15th March detailing the diagnostic path and an appropriate software update that should be followed.

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.