

Reference	SSM73291
Models	Discovery Sport / L550 Range Rover Evoque / L538
Title	L550 & L538 9HP48 9-speed with P2545-86 and/or P2546-86 DTC's stored
Category	Driveline
Last modified	16-Mar-2017 00:00:00
Symptom	501000 Automatic Transmission Concerns

Content

Concern:
Discovery Sport (LC) 2015MY Onwards & Range Rover Evoque (LV) 2014MY Onwards fitted with 9HP48 9-Speed Automatic Transmission: Retailers reporting these vehicles are flagging the following (TCM) **Transmission control module** DTC's **P2545-86 and/or P2546-86** codes during SDD DTC read or on customer concern.
Should there be any other transmission related fault codes stored in the TCM these other codes should be investigated and resolved before proceeding with this instruction.

Issue:
Under Investigation.

Action:
Any retailer seeing this DTC P2545-86 and/or P2546-86 firstly check the transmission for any oil leaks and repair as required. If no oil leaks are evident check the oil level and repair as required, update the TCM software where an update is available, and clear the DTC. If the DTC does not re-log no further action required return to customer.
If the DTC is repeatable then provide the original session file and the latest session file showing the DTC detail and request technical assistance (T.A).

Technicians - Please rate this SSM and provide comments so that future communications can be improved.

1 = Poor – Basic information provided – The SSM does not help me resolve the customer concern.

3 = Average – Adequate information provided – The SSM partially helps me resolve the customer concern.

5 = Excellent – All required information provided to resolve the customer concern.