

January 17, 2016

05640 Version 2

Torque Converter Shudder

This bulletin is replaced by S/B 16-060, *Product Update: 2011 RL Software Update for Lock-up Clutch Function*

If you did Service Bulletin 16-003 on or before January 17, 2017. Make sure to use Warranty Claim Information provided below.

WARRANTY CLAIM INFORMATION

The normal warranty applies.

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
218100	Replace the torque converter.	8.2 hrs	03214	04501	16-003N	26000-RP7-305

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
218100	Replace the torque converter.	8.2 hrs	03214	04501	16-003P	26000-RP7-305
E	Align the vehicle - add	0.4 hr				

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
218100	Replace the torque converter.	8.2 hrs	03214	04501	16-003Q	26000-RP7-305
H	Update the PCM software - add	0.2 hr				

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
218100	Replace the torque converter.	8.2 hrs	03214	04501	16-003R	26000-RP7-305
E	Align the vehicle - add	0.4 hr				
H	Update the PCM software - add	0.2 hr				

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.