

April 26, 2017

06103 Version 3

Transmission Slips or Shifts Hard When Cold

This bulletin is replaced by 17-015, *8-Speed DCT Has a Bump or Hard Shift When Coming to a Stop*

All vehicles affected by this bulletin were superseded to 17-015.

If you did Service Bulletin 15-021 on or before April 26, 2017, make sure to use the Warranty Claim Information provided below to file a claim.

WARRANTY CLAIM INFORMATION

The normal warranty applies

Operation Number	Description	Flat Rate Time	Defect Code	Symptom Code	Template ID	Failed Part Number
1255C9	Update the PCM A/T software and do the clutch break-in procedure twice	0.7 hrs	03214	03230	15-021N	37820-RDF-A54

Skill Level: Repair Technician

CLIENT INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Acura automobile dealer.