

## **Service Bulletin**

File in Section:

Bulletin No.: 16-NA-229

Date: July, 2016

## **INFORMATION**

Subject: Information on Perceived Lumbar Back Massage Inoperative or Poor Performance

Ī	Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
	Diallu.	woder.	from	to	from	to		
	Buick	LaCrosse	2017	2017			All	All

Involved Region or Country	NORTH AMERICA, CHINA			
Additional Options (RPO)	Equipped with CONTROL-SEAT, MASSAGE, DRIVER and PASSENGER (RPOs AF6 and AKE)			
Condition	Some customers may comment that the lumbar back massage is inoperative or exhibiting poor performance.			
Cause	The back massage intensity works in conjunction with the lumbar adjustment of the seat.  The cause of the condition may be that the lumbar adjustment of the seat may be in a decreased setting, which gives the perception that the massager is not functioning or is operating ineffectively.			

## **Customer Information**



**Note:** The location of the driver side seat lumbar adjustment control (1) and the message button (2) are shown in the graphic above.

Please communicate to the customer that the seat system is working as designed, however they can improve the intensity of the back massage by increasing the lumbar adjustment**prior** to activating the massage. The customer can also find further information in the Seats and Restraints section of their Owner Manual under *Lumbar Adjustment* and *Massage*.

Please share this information with the customer, including a copy of this message.

4552293

Version	1
Modified	