



# Service Bulletin

File in Section: -

Bulletin No.: 16-NA-232

Date: July, 2016

## INFORMATION

**Subject:** Information on Appearance of Driver Seat Back Inboard Side Panel

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2013	2017			All	All
Chevrolet	Traverse	2013	2017			All	All
GMC	Acadia	2013	2016			All	All
GMC	Acadia Limited	2017				All	All

<b>Involved Region or Country</b>	North America, Middle East, Chile, China, Israel
<b>Condition</b>	 <p style="text-align: right; font-size: small;">4557718</p>
<b>Cause</b>	This may be due to the inboard seat side airbag in this area creates a difference in appearance when compared to the passenger seat inboard panel.

### Correction

This is a normal appearance and **NO** adjustment or replacement of the airbag should be made for this concern.

The inboard seat airbag is mounted in this area and creates a slightly different contour of the seat.

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, **DO NOT** assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION