



Service Bulletin

INFORMATION

Subject: Tire Pressure Monitor (TPM) Concerns After Accessory Wheel Installation

Models: 2016-2017 GM Passenger Cars and Light Duty Trucks with Accessory Wheels

This PI has been revised to update the Model Years and update the applicable information below. Please discard PI1385.

Condition/Concern

Some customers may comment that the tire pressure monitor (TPM) indicator is illuminated on the cluster.

This may be caused by the TPM sensors not being relearned after the installation of accessory wheels or incorrect/defective TPM sensors supplied with the wheel/tire assemblies from the Accessory Distributor Installer (ADI).

Recommendation/Instructions

The TPM sensors must always be relearned when accessory wheels are installed on the vehicle.

If the learning process does not resolve the issue and it is found to be a defective and/or incorrect sensor, the dealer should resolve this with the supplying ADI.

Note: There is an expectation that the correct/functional TPM assembly will be supplied by the ADI with the accessory wheel. If it is found this is not true, the dealer and ADI should resolve this condition and this should not be charged to warranty.

Note: Installation time includes the time to relearn the TPM sensors and this should be completed during the accessory installation. If the TPMs were not relearned at installation, this should not be charged to warranty.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY TECHNICIAN CERTIFICATION