



Service Bulletin

File in Section: -

Bulletin No.: 16-NA-167

Date: May, 2016

TECHNICAL

Subject: Low Washer Solvent With No Low Washer Solvent Message Displayed

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Cascada	2016	2016			All	All

Involved Region or Country	North America
Condition	Some customers may comment that they run out of washer fluid and did not receive a message displayed on the DIC.
Cause	This may be due to the XML code for the cluster did not have "Low Washer Fluid" message enabled.

Correction

If you encounter a vehicle with the above concern, please perform IPC - Configuration & Setup. Refer to *Instrument Cluster Programming and Setup* in SI.

Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
2810195	Instrument Cluster Reprogramming with SPS	Use Published Labor Operation Time

Version	1
Modified	

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION