

MIL Comes On and Stays On After Installing the Fuses at TQI

AFFECTED VEHICLES

2017 MDX Sport Hybrid

Is the MIL coming on and staying on after installing the No. 15 RADIO (20 A) and No. 16 BACKUP (10 A) fuses at TQI? We're aware of this issue and are looking for a solution.

Until then, here's what you can do to handle this:

1. Make sure the parking brake is applied and the transmission is in Park.
2. With your foot firmly on the brake pedal, press the POWER button. Wait for the READY indicator to come on.
3. Press and hold the POWER button. Wait for the READY indicator to go off.
4. Repeat steps 2 and 3 **five** times or more. The MIL should go off. But if it doesn't, then continue with normal system troubleshooting.