



GROUP  
BOD

MODEL  
2017MY  
Forte (YDm)

NUMBER  
157

DATE  
December 2016

## TECHNICAL SERVICE BULLETIN

**SUBJECT:** SERVICE ACTION: REAR COMBINATION  
LAMP WATER INTRUSION (SA256)

This bulletin provides the procedure to replace the outer rear combination lamp pads on some 2017MY Forte (YDm) vehicles, produced from May 24, 2016 to October 13, 2016, which may exhibit evidence of water intrusion in the outer rear combination lamps. Follow the procedure outlined in this bulletin to replace both left and right outer rear combination lamp pads. Before conducting the procedure, verify that the vehicle is included on the list of affected VINs.



### \* NOTICE

A Service Action is a repair program with customer notification that is performed during the warranty period. Any dealer requesting to perform this repair outside the warranty period will require DFR approval.

Repair status for a VIN is available on WebDCS (Service → Warranty Coverage → Warranty Coverage Inquiry → Campaign Information). Not completed Recall / Service Action reports are available on WebDCS (Consumer Affairs → Not Completed Recall → Recall VIN → Select Report), which includes a list of affected vehicles.

This issue number is SA256.

File Under: <Body>

Circulate To:  General Manager  Service Manager  Parts Manager  
 Service Advisors  Technicians  Body Shop Manager  Fleet Repair