



Preliminary Information

PIP5542 Malfunction Indicator on - P2B95

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Malibu	2018	All	All	1.5L (RPO LfV)	All
Involved Region or Country		North America				
Additional Options (RPO)		None				
Condition		Malfunction Indication Lamp On - P2B95				
Cause		GM is currently evaluating the concern.				

Correction:

If you encounter the vehicle listed above with a P2B95 set in the ECM, perform the SI diagnostic.

If the SI diagnostic fails to isolate the root cause, do not attempt repairs at this time.

Clear the DTC and Release the vehicle to the customer.

Please communicate to the customer that we apologize for this inconvenience and that General Motors is currently evaluating this concern.

This PI will be updated with additional details as they become available.

Version History

Version	1

