

[Next Unread Message](#)

View Message

Sent on 02 14 2018 **Expires on** 02 28 2018

From Parts and Service Division

Subject Request for Parts: 2018 Accord 2.0 Turbo Disconnected Intercooler Hose

PRIORITY/ACTION REQUIRED

To: All Honda Service Managers/Advisors
From: Technical Research & Support Group
RE: Request for Parts: 2018 Accord 2.0 Turbo Disconnected Intercooler Hose

This message is solely directed to Honda dealership personnel; please handle accordingly.
Print this *iN* message and provide a copy to the Shop Foreman and all Service Advisors.

Background

American Honda Motor Co., Inc. (AHM) is investigating certain 2018 Accord 2.0 Turbos with a customer complaint of delay in acceleration and MIL on. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. Vehicle must be 2.0 Turbo.
2. Confirm that the intercooler hose is disconnected (do not attempt to reinstall).
3. No repair has been attempted for this issue.

Action Required

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.