

[Next Unread Message](#)

View Message

Sent on	02	14	2018	Expires on	02	28	2018	
From	Parts and Service Division							
Subject	Request for Parts: 2017-2018 CR-V Radar Misaligned with DTC P2583-76 Stored							

PRIORITY/ACTION REQUIRED

To: All Honda Service Managers/Advisors
From: Technical Research & Support Group
RE: Request for Parts: 2017-2018 CR-V Radar Misaligned with DTC P2583-76 Stored

This message is solely directed to Honda dealership personnel; please handle accordingly.
Print this i/V message and provide a copy to the Shop Foreman and all Service Advisors.

Background

American Honda Motor Co., Inc. (AHM) is investigating certain 2017-2018 CR-Vs with a customer complaint of various warning lights such as the brake system, lane departure, ACC & forward collision warning illuminated on the dash with the DTC P2583-76 (Temporary stop of Integrated Driver System – Misalignment Millimeter Wave Radar) stored. To fully understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind except to confirm conditions stated in the Qualifiers below before calling TRS.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirement:

- 1. VIN must start with 2HK.
- 2. Customer reported one or more of the warning lights.
- 3. DTC P2583-76 must be stored.
- 4. Attempt to clear the DTC, but the DTC remains.
- 5. Inspect radar alignment clips for proper setting. If the clips are found to be broken/damaged please take pictures before removing.

Action Required

If you have or know of such a vehicle, please call the Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.