



Preliminary Information

PIC6324 Left Side Blind Zone Indicator Comes on Randomly While Driving with No Objects Present

Proactive

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Encore	2018	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	UFT
Condition	A customer may notice that the left side blind zone indicator comes on randomly while driving without any objects present. It is possible that the indicator may stay on for an extended amount of time.
Cause	Engineering is investigating this concern

Correction:

Engineering is aware and currently working on this issue. The PI will be updated when a repair is available.

Version History

Version	1
Modified	Created on 2/12/2018

