



Preliminary Information

PIP5556 GF9 NON-ETRS Transmission Assembly With Intermittent DTC P2731

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Traverse	2018	ALL	ALL	ALL	M3V (GF9)
Chevrolet	Equinox	2018	ALL	ALL	ALL	M3D (GF9)
Involved Region or Country	North America					
Condition	Vehicle's equipped with a GF9 NON-ETRS trans assembly may have an intermittent DTC P2731.					
Cause	Slow OWC release on a rolling re-accel at low speeds.					

Correction :

Engineering is aware of this concern and is validating a repair.

If DTC P2731 is not set as a hard fault, and there are no drivability concerns, no repairs should be attempted at this time.

If drivability concerns are present, and/or DTC P2731 is set as a hard fault, follow SI diagnostics as needed.

This P/I will be updated or advanced to a TSB when a repair has been validated.

Version History

Version	1
Modified	

