



Preliminary Information

PIP5514A Malfunction Indicator Lamp MIL On DTC P0705 Or P0706 Set

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Spark	2016 - 2018	All	All	All	MR8
Involved Region or Country	North America					
Additional Options (RPO)	None					
Condition	Some customers may comment on the operation or performance of the CVT7 transmission and/or the SES light is illuminated.					
Cause	Technicians may find codes P0705 or P0706 set in the TCM.					

Correction:

Please do not perform the service fast learn procedure as it will not address either one of these codes.

Please follow service information to aid in diagnosing codes P0705 or P0706.

Service Procedure:

If diagnostics leads to replacement of the transmission range sensor engineering is temporarily asking to please replace the TCM also.

Note: This information will be updated after engineering has collected enough data to aid in finding root cause of these codes setting.

Note: As written above please do not perform a service fast learn procedure with the old TCM in place. The fast learn procedure will not address these codes and the data that engineering is looking for will be lost.

Note: Engineering will be requesting both the transmission range sensor and the TCM be returned to the WPC.

Version History

Version	2
Modified	02/20/2018 Added the 2018 MY and a note advising not to perform the SFL procedure.

