



Solution

Title (customer effect)	Mack Chassis - Diesel Exhaust Fluid (DEF) System Cleaning/Flush After DEF Pump Failure Or System Contamination
Cause	Procedure for cleaning the DEF system after a pump failure or contamination.
Solution	Refer to Operation ID 2589-11-02-05 under the Service tab in Impact for proper flushing of contamination in the DEF system.
Solution visibility	Dealer distribution
Function(s)/component(s) affected	
Function affected	engine , exhaust
Function Group	
Function Group	258 emissions after-treatment
Customer effect	
Main customer effect	diagnostics/methodology , efficiency/abnormal behavior , visual appearance
Fluid problem	leak , contamination
Fluid implicated	AdBlue
Visual appearance	leaking
Administration	
Author	a175606
Last modified by	RU4469V
Creation date	05-04-2016 18:04
Date of last update	04-01-2018 21:01
Status	Published
NA_MACK_Vehicle_Range	
NA_MACK_Vehicle_Range	Cabover , LR , LEU , MRU , Conventional , Anthem , CHU , CXU , GU , TD
Engine family	
Engine family	Mack , MP7 , MP8 , MP10
Emission Standard	
Emission Standard	2018 , OBD2017 , US17 GHG , US16 , US15 , US10 , US13 OBD , US14 GHG